

Fig. 2





Fig. 3






Fig. 5

RTD₂
SN
RTD₁
RTD₁
RTD₂
V_{ref*}
V_{SN}

Fig. 6






Fig. 7



ocket No.: 02893-036001


Fig. 8





The Control of the Co

ocket No.: 02893-036001

Fig. 9










Fig. 13




Fig. 14




Fig. 15





Fig. 16








Fig. 18

in the state of

Fig. 17








Fig. 19

